

**TABLE 2.4
SUMMARY OF STREAM CHARACTERISTICS WITHIN THE WETLAND DELINEATION STUDY AREA**

<i>Stream/Seep Number</i>	<i>General Location</i>	<i>Watershed</i>	<i>Defined Stream Bed and Banks (Y/N), comments</i>	<i>Average width (feet)</i>	<i>Average Depth (feet)</i>	<i>Intermittent or Perennial (I/P)</i>	<i>Fish Habitat (Yes/No)</i>	<i>Aquatic Macroinvertebrate Habitat ⁽¹⁾</i>	<i>Dominant Substrate</i>	<i>Wetlands Adjoining Stream Segment</i>
1	Between WGT 5 and 6	Town Brook	N, seep on logging road	1	0.1	I	No	None	Bedrock	No
2	Pickens Road	UNT to Town Brook	Y, downstream of flag 53, north of Pickens Road	2	0.5	I	No	Limited	Bedrock, cobble, silt	No
3	Pickens Road	UNT to Town Brook	Y, downstream of flag 59, north of Pickens Road	2	0.5	I	No	Limited	Bedrock, cobble, silt	No
4	Pickens Road	UNT to Town Brook	Y, south of Pickens Road	2	0.5	I	No	None	Bedrock, cobble, silt	No
5	Pickens Road	UNT to Town Brook	N, seep	1	0.2	I	No	Yes	Bedrock, cobble, silt	Yes
6	Pickens Road	UNT to Town Brook	N, seep on and along road	1	0.1	I	No	Limited	Bedrock, cobble, silt	Yes
7	Pickens Road	UNT to Town Brook	N, seep on and along road	1	0.1	I	No	Limited	Bedrock	Yes
8	Pickens Road	UNT to Town Brook	Y, road side ditch	2	1	I	No	Limited	Bedrock, cobble, silt	No
9	Pickens Road	UNT to Town Brook	Y, road side ditch	2	1	I	No	Limited	Bedrock, cobble, silt	No
10	North of Brockway Road	UNT to Town Brook	Y, south of existing farm lane at flag 159	2	2	I	No	Limited	Silt, soil	Yes
11	Davis Road	UNT to Town Brook	Y, springs and road side ditch	2	0.5	I	No	Limited	Bedrock, cobble, gravel	Yes
12	Davis Road	UNT to Town Brook	Y, road side ditch	1	1	I	No	Limited	Bedrock, cobble, gravel	No
13	Davis Road	Town Brook	Y, Town Brook main stem	5	2	P	Yes	Yes	Cobble, gravel, sand	Yes
15	Davis Road	UNT to Town Brook	Y, south of Davis Road	1	0.5	I	No	Limited	Bedrock, cobble, silt	Yes
16	Davis Road	UNT to Town Brook	Y, south of Davis Road	1	0.5	I	No	Limited	Bedrock, cobble, silt	Yes
17	Davis Road	UNT to Town Brook	N, seep on road	0.5	0.1	I	No	No	Bedrock	No
18	Davis Road	UNT to Town Brook	Y, road side ditch	1	1	I	No	Limited	Bedrock	No

1. No = No suitable aquatic macroinvertebrate habitat
Limited = Limited by the intermittent / ephemeral nature of flow and poor habitat
Yes = Suitable habitat is present for aquatic macroinvertebrates